and the same of th	esday, 4/18/2006 10:07:02 AM m Johnston			Split Oblio 120
7		Process Sheet	Se	06/10/0
Customer Job Number Estimate Number P.O. Number This Issue Prsht Rev. First Issue Previous Run Written By Checked & Appro	: NC : NC : NC : NC : 24712 Dived By : Est: A 0400.07 New I	Part Number Drawing Number Project Number Drawing Revision Material Due Date	: D3303043 : D3303 REV. A : N/A	E Um: Eac
Additional Produ	ct			
Job Number:			<b>.</b>	
Seq. #:	Machine Or Operation:	Description :		
1.0	D33031	Plate		
Com	nent: Qty.: 1.0000 Each(s)/Unit T PLATE Pick: Qty Part Number Descr 1 D3303-1 Plate	ription  Batch  Batch		
2.0	D33033	Bracket		
Comm	nent: Qty.: 1.0000 Each(s)/Unit T BRACKET Pick: Qty Part Number Descri 1 D3303-3 Bracke	iption Batch		
3.0	MS20426AD33	Rivet		
Comn	nent: Qty.: 8.0000 Each(s)/Unit To RIVET Pick: Qty Part Number Descri 8 MS20426AD3-3 Rivet	1996		
4.0	MS20470AD44	Rivet, Universal Head		rh
Comm	nent: Qty.: 16.0000 Each(s)/Unit T Rivet, Universal Head Pick:	otal: 112.0000 Each(s)		

Qty Part Number

Description

Batch

Tuesday, 4/18/2006 10:07:02 AM e: Kim Johnston ser: **Process Sheet** Drawing Name: BRACKET ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Part Number: D3303043 Job Number: 26690 Job Number: Description: Seq. #: Machine Or Operation: 12 MS20470AD4-4 Rivet MS21075L3 Nutplate 5.0 28.0000 Each(s) 4.0000 Each(s)/Unit Total: Comment: Qty.: Nutplate Pick: M18534 Description Qty Part Number Nut Plate MS21075L3 SMALL FAB 1 6.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 1- Assemble as per Dwg D3303 2- Identify as D3303-043 INSPECT WORK TO CURRENT STEP 7.0 QC5 Comment: INSPECT WORK TO CURRENT STEP POWDER COATING 8.0 POWDER COATING 9720 Comment: POWDER COATING Powder Coat Grey Sandtex (Ref: 4.3.5.6) as per QSI 005 4.3 \*\*\*\*MASK THREADS PRIOR TO PAINT\*\*\*\* INSPECT POWDER COAT/CHEMICAL CONVERSION 9.0 QC3 Comment: INSPECT POWDER COAT PACKAGING RESOURCE PACKAGING 1 10.0 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 51422 11.0 Comment: DOCUMENT CONTROL Inspection Level 21 Job Completion Page 2 Form: rprocess